POI 09-01V

Pag 1/1

DIESSE DIAGNOSTICA SENESE SpA 53035 Monteriggioni (SI) – Italia – Via delle Rose 10 Tel +39-0577-587111 Fax +39-0577-318690



Sede Legale e Amministrazione 20144 Milano (Italy) Via A. Solari 19 sc. 6 Tel. +39-02-4859121 r.a. Fax +39-02-48008530

PRODUCT NAME:

VACU-TEC

| Code | 10208 | | | | |
|-----------|-------------|---|---------|----|---------|
| Lot No | 2327 | Ω | 2023-09 | سا | 2022-11 |
| Reference | ce IO-09/88 | | | | |

| ON | LINE QUALITY CONTROLS (model CDP not enclosed) | | | 00 P I | |
|---|--|-----------|---------|-----------|-----|
| | | | | QC Passed | |
| | sodium citrate solution concentration | | | ₩ | |
| = | sodium citrate volume | | | ᅜ | |
| | vacuum level (*) | | | ত | |
| = | correct placement of the cap | | | ▽ | |
| - | no extra body inside the product | | | ₽ | |
| (*) | Only for VACU-CODE and VACU-TEC tubes | ₽ | | | |
| PA | CKAGING QUALITY CONTROL (model CDP not enclosed |) | | QC Passed | |
| • | control of the number of the product for each pack | | | ▽ | |
| QU | ALITY CONTROLS ON FINISHED PRODUCT (model CDF | onot en | closed) | | |
| | | | | QC Passed | |
| | pack integrity | | | v | |
| | data printed on the product label | | | ଷ | |
| | | | | QC Passed | N/A |
| Irradiation treatment Certificate n° date | | | | L. | Þ |
| | | | | QC Passed | N/A |
| | nma rays treatment process in compliance with the spe he supply Agreement | ecificati | ons | Г | ত |
| Document number: | | ODV | N.A. | | |

This batch has been manufactured and checked according to quality requirements. Hereby, it is released to distribution.

APPROVED

RESPONSIBLE HEAD, Quality Control Reagents.....

DATE 24/11/2022