Pag 1/1

DIESSE DIAGNOSTICA SENESE SPA 53035 Monteriggioni (SI) – Italia – Via delle Rose 10 Tel +39-0577-587111 Fax +39-0577-318690



Sede Legale e Amministrazione 20144 Milano (Italy) Via A, Solari 19 sc. 6 Tel, +39-02-4859121 r.a, Fax +39-02-48008530

PRODUCT NAME:

VACU-TEC

| Code | 10208 | | | | |
|-----------|------------|----------|---------|-------------------------|---------|
| Lot No | 2242 | Σ | 2023-06 | $\qquad \qquad \cdots $ | 2022-08 |
| Reference | e IO-09/88 | | | | |

| ON | INF CHALITY CONTROL (/ mandal ODD and amale and) | | | | |
|--|--|--------------------|------|-----------|----------|
| ON LINE QUALITY CONTROLS (model CDP not enclosed) | | | | QC Passed | |
| * | sodium citrate solution concentration | V | | | |
| × | sodium citrate volume | | (V | | |
| н | vacuum level (*) | | liv. | | |
| н | correct placement of the cap | | • | | |
| * | no extra body inside the product | | (J | | |
| (*) C | nly for VACU-CODE and VACU-TEC tubes | i₽ | | | |
| PAC | KAGING QUALITY CONTROL (model CDP not enclosed) | QC Passed | | | |
| an . | control of the number of the product for each pack | ø | | | |
| QUA | LITY CONTROLS ON FINISHED PRODUCT (model CDF | QC Passed | | | |
| M: | pack integrity | ₩ O F dSSeU | | | |
| ж | data printed on the product label | Ø | | | |
| | | | | QC Passed | N/A |
| Irradiation treatment Certificate n° date | | | | F | Þ |
| | | | | QC Passed | N/A |
| Gamma rays treatment process in compliance with the specifications of the supply Agreement | | | | Ē. | ₽ |
| Document number: ODV N.A. | | | N.A. | | |
| | | | | | |

This batch has been manufactured and checked according to quality requirements. Hereby, it is released to distribution.

APPROVED

RESPONSIBLE HEAD, Quality Control Reagents.....

DATE0.1... 09/2020