#### DIESSE DIAGNOSTICA SENESE SPA

878

53035 Monteriggioni (SI), Italy, Strada dei Laghi 39 Tel. +39 0577319554 FAX +39 0577319020



M 2022-10

Sede Legale 20144 Milano (Italy) Via A, Solari 19 sc. 6

# QUALITY CONTROL CERTIFICATE GLIADIN-G - CHORUS

## REAGENTS

KIT NAME

Code

Lot No.

abel	Description	Lot.	Exp.	NO	
D3411	Gliadin-G	878	2023-10	6X6	
B3411	CALIBRATORE Gliadin-G	878	2023-10		
C3411	CONTROL SERUM Gliadin-G	878	2023-10	1	


#### CONTROLS

Found results	Expected results

2023-10

CALIBRATOR (mOD)	466	≥ 100
CONTROL SERUM (AU/ml)	36,6	21,4-55,6


#### CALIBRATOR



Label checked with barcode reader

YES \

Operator Signature ... 80



#### CONTROL SERUM

5	0	2	8	7	8	6	1	2	2	2	0	0	0	0	0	0	1
										1							- 1

Label checked with barcode reader

YES Operator Signature ......



This batch has been manufactured and checked according to quality requirements. Hereby, it is released to distribution.

APPROVED RESPONSIBLE HEAD, Quality Control Reagents...

DATE 21 M GR

### WARNING: POTENTIAL BIOHAZARDOUS MATERIAL!

This kit may contain some reagents made with human serum or plasma. All serum or plasma used has been tested and found non-reactive for HIV-1/2, HCV and HBsAg, Because no method can offer complete assurance that HIV-1/2, HCV, HBsAg or other infectious agents are absent, reagents should be handled with maximum attention.